

**PHOTOGRAPHIC ANALYSIS VIEWPOINTS AND LOCATIONS**

PHOTOS TAKEN BY HILDERMAN THOMAS FRANK CRAM MAY 2006

**FIGURE 1B**



1 Smith Street Edge Condition Inaccessible.




2 View Upon Entering from Donald Obstructed.



3 Typical Seating Condition Poor.



4 Spatial Orientation Lack of signage & wayfinding cues.



5 Donald Street Exit Limited safety & visibility.



6 Interior Park Space Broken views & connections



7 Smith Street Edge Condition Wall typical.



8 Interior Park Plaza  
Isolated from the street & empty.



9 Internal Circulation  
Convoluted & confusing.



10 Internal Circulation  
Convoluted & confusing.




11 Central Space  
Pool not functional or safe.



12 St. Mary Avenue Access  
No sense of entry, connection or gateway.



13 St. Mary Avenue Access  
Indirect, no wayfinding cues.



14 Donald Street Parking Access  
The car dominates.



15 Library Courtyard  
Unsafe & unrepaired from previous construction.



16 Smith Street Parking Access  
The car dominates.



17 Plaza Detail  
Deteriorating materials.



18 Smith & Graham Entrance  
Poor visibility.



19 Smith & Graham Exit  
Not pedestrian friendly.



20 Donald & Graham Entrance  
Conflicting uses & poor wayfinding.



21 Donald & Graham Exit  
Conflicting uses & poor wayfinding.



22 Donald Street Exit  
Limited safety & visibility.